

FIG. 1 RELATED ART






MAGNETIC DISK DRIVE HAVING A SURFACE COATING. . . Watanabe et al. Greer, Burns & Crain, Ltd. Ref. No. 0941.64850 Sheet 3 of 16 (312) 360 0080

FIG. 3 RELATED ART

<u>11</u>



MAGNETIC DISK DRIVE HAVING A SURFACE COATING. . . Watanabe et al. Greer, Burns & Crain, Ltd. Ref. No. 0941.64850 Sheet 4 of 16 (312) 360 0080

FIG. 4 RELATED ART





FIG. 5



MAGNETIC DISK DRIVE HAVING A SURFACE COATING. . . Watanabe et al. Greer, Burns & Crain, Ltd. Ref. No. 0941.64850 Sheet 6 of 16 (312) 360 0080

FIG. 6A





FIG. 6B






FIG. 8A




FIG. 8B






FIG. 8C



MAGNETIC DISK DRIVE HAVING A SURFACE COATING. Watanabe et al.
Greer, Burns & Crain, Ltd.
Ref. No. 0941.64850
Sheet 9 of 16 (312) 360 0080

FIG. 9



MAGNETIC DISK DRIVE HAVING A SURFACE COATING. Watanabe et al.
Greer, Burns & Crain, Ltd.
Ref. No. 0941.64850
Sheet 10 of 16 (312) 360 0080

FIG. 10






FIG. 11




MAGNETIC DISK DRIVE HAVING A SURFACE COATING. . Watanabe et al.
Greer, Burns & Crain, Ltd.
Ref. No. 0941.64850
Sheet 12 of 16 (312) 360 0080

FIG. 12



MAGNETIC DISK DRIVE HAVING A SURFACE COATING.
Watanabe et al.
Greer, Burns & Crain, Ltd.
Ref. No. 0941.64850
Sheet 13 of 16 (312) 360 0080

FIG. 13








FIG. 14

40
51
53
52A
52B
52
40A

FIG. 15



40



MAGNETIC DISK DRIVE HAVING A SURFACE COATING. . . Watanabe et al. Greer, Burns & Crain, Ltd. Ref. No. 0941.64850 Sheet 16 of 16 (312) 360 0080

FIG.17

